

Core switch cannot find ports



Overview

Step-1 Please make sure your network cable is good first Step-2 Please power cycle the switch and boot into the ACCTON-DIAG for troubleshooting Step-3 Enter the command to set port speed Set the port speed to 25G and 100G on the uplink ports. If you issue no switch on the interface, the interface will be configured as Layer3 interface and one IP address is expected. One good practice is add the command "spanning-tree portfast " on this. We have a pair of Dell N3224P-ON switches and today's morning my colleague gave me a task and instructions to remove some unused VLANs. I'm sure I removed the correct VLANs. 1 My problem is : If i connect any Pc or device to core witch port i cannot ping it, I have first enable the ICMP stream in. The diagram only shows one connection from the edge switch to the core switch, so when one switch goes down you are always going to isolate at least one switch. There is zero documentation to top it off! I know that the 'Clear counters' command is useful here, but is there.

Core switch cannot find ports



We have a Huawei Core switch and a Dlink plug and play switch before the new Huawei Access switch was deployed. I discovered that everyone on the Core Switch and Dlink Switch is all ...



I suggest you create SVIs on the core switches, establish port-channels between the core switches and create a Layer3 mesh between them advertising routes via IGP.



We have a pair of Dell N3224P-ON switches and today's morning my colleague gave me a task and instructions to remove some unused VLANs. I'm sure I removed the correct VLANs. When I saved ...



This document describes how to determine why a port or interface experiences problems.



If the 1G copper port CANNOT link up, please cross-test with other ports as well. If there are some specific ports still has problem, then please return the unit back for RMA repair service.




there is no possibility of pinging from one VLAN to another VLAN without routing between them. By default, any router has ICMP enabled.



If i connect any Pc or device to core witch port i cannot ping it, I have first enable the ICMP stream in the device firewall or windows firewall. before it''s working without icmp but after i ...



Purpose : This article describes how to troubleshoot the switch ports cannot link up problems. Model : AS5835-54X Procedure : Step-1...



I've been told "Show interfaces" by a colleague, but it outputs a lot of information that I find hard to read through, and with 13 switches to get through across the site its going to take a long time.



If you issue no switch on the interface, the interface will be configured as Layer3 interface and one IP address is expected. With the second option you keep the interface as Layer2 and use ...

Contact Us

For more information, pricing, or custom solutions, please contact us:

Website: <https://indzawo.co.za>

Email: sales@indzawo.co.za

Phone: +27 71 296 8473

Address: 22 Quantum Street, Midrand, 1685, Gauteng, South Africa

This document is for informational purposes only. Specifications subject to change without notice.

